Ferry Maintenance Report – Spirit of Vancouver Island



Vessel: Spirit of Vancouver Island

Date: 2016-09-21

Arrival: 10am Swartz Bay terminal

Reporter: Rowan Fox Staff: Kathryn Purdon, Will Glatt, Rowan Fox

Reason for Visit

Clean instruments, do benchmarks on BBFL2 and optode, investigate alignment of wind sensor on met station.

Observations

- Instrument housing was very dry, no signs of leaking, after last visit's swap out of the pump.
- Met station is rotated ~5 degrees from the center line. Needs alignment.
- Sea Strainer is leaking, will need replacement. See Photos.

Actions Taken

- 1. Opened up PC box, shut down system at about 11:30 PDT.
- 2. Removed instruments for cleaning: BBFL2, TSG, optode. Did benchmarks on BBFL2 and optode. Benchmark files are uploaded to Alfresco into device folders: BBFL2 SN785 AADI3835 SN1416
- 3. Rinsed and cleaned seastrainer. Noted leaks around the mating surface of the top cap and the lower section. This will need to be replaced next trip.
- 4. Replaced tubing.
- 5. Reinstalled instruments and started system, no leaks detected.
- 6. Replaced dessicant, closed up both instrument box and computer box.
- 7. Went up to the met station. Noted that the wind sensor base is rotated about 5 degrees to the left of the ship's center line towards the bow. Everything else appeared fine.
- 8. Kathryn made measurements of the met station's height above the seawater.

Future Actions (High Priority in Red)

Replace sea strainer.

Pictures



















