Ocean Networks Canada

Date: 2016-07-14

Ferry Maintenance Report – Queen of Oak Bay

Vessel: Queen of Oak Bay

<u>Arrival:</u> We signed in at Departure Bay terminal supervisor at 7:45, got on ferry for 8:30 departure. Arrived back at Departure Bay at about 12:40.

Reporter: Rowan Fox Staff: Akash Sastri, Rowan Fox

Reason for Visit

Instrument cleaning and benchmarking. Test fit of new BBFL2 housing, swap housings if possible.

Observations

- System dry and running properly on arrival.
- BBFL2 housing does not fit. Housing is too long. Solution return housing to machinist, chop 1 inch off the bottom, cut new Oring groove and threads.
- TSG missing a screw on one of its posts, but the post has no hole to accept the screw thread.
 Probably not an issue.
- After this trip, we found that the Optode has experienced a memory wipe. This occurs when it loses power while saving settings. As a result, all settings on the optode revert to zero. Optode is to be replaced ASAP. See INST-931

Actions Taken

- 1. Sign in Engineering room
- 2. Shut off output gate valve, otherwise system pressure causes constant water flow from open tubes.
- 3. Cleaned and performed benchmarks on optode and BBFL2.
- 4. Cleaned out TSG, had some sediment in it.
- 5. Cleaned seastrainer.
- 6. Tried new BBFL2 housing. Failed to fit it in. Reinstalled old housing.
- 7. Opened output gate valve, started system, verified no leaks.
- 8. Installed new dessicant.
- 9. Closed up seakeeper system.

Future Actions (High Priority in Red)

- Modifications to BBFL2 housing
- Bring a small bucket to empty/flush seastrainer
- Replace Optode
- Stephen to see if there is a place we can store tools on the ship. Follow up

Ferry Maintenance Report – Queen of Oak Bay

Pictures



Ocean Networks Canada

Ferry Maintenance Report – Queen of Oak Bay















Ocean Networks Canada

Ferry Maintenance Report – Queen of Oak Bay

