Ferry Maintenance Report – Queen of Oak Bay



Date: 01/12/2016

Staff: William Glatt, Evan Poulton, Stephen Phillips

Ship's crew:

Reason for Visit

Reporter: William Glatt

- Instrument Benchmarks •
- Installation of new anti-vibration mounts on SAS AUX BOX

Observations (important highlighted in red)

System operating in a normal state. All dry inside instrument box

Optode – removed for benchmark and cleaning. Readings indicate normal functioning

BBFL2 – Similar to previous reports, housing showing signs of stress and benchmark readings were within tolerance

TSG - Sensor was fairly clean, simple rinse with fresh water sufficed for cleaning

Actions Taken

- 1. Arrived at Departure Bay at 0755 parked in lane 34. Signed in with Customer Service counter.
- 2. Boarded ship, checked in with Chief Steward and signed into engine room
- 3. Opened computer box and instrument chest. Observed system in normal operating mode
- 4. Shut down Sea Keeper computer
- 5. Began disassembly
- 6. Performed benchmarking
- 7. Cleaned TSG
- 8. Replaced instruments and cut new tubing for manifold distribution

9. Went above bridge #2 while seakeeper system was powered down and disassembled SAS AUX box mounting plate

10. Replaced anti-vibration mounts and remounted SAS AUX BOX

11. Returned to Engineering dept and powered up Seakeeper system, checked for leaks and data acquisition

Ocean Networks Canada Ferry Maintenance Report – Queen of Oak Bay

Future Actions

Discuss with ferry maintenance team having new BBFL2 housings machined

Pictures













